
1995 GULFSTREAM IV/SP

AIRFRAME: 6214.0 Hours
LANDINGS: 3240
APU: GTCP 36-150 Upgrade c/w 125.0 Hours
(APU on MSP Program)
MAINTENANCE: 72 month inspection
completed
at Gulfstream July 2007

ENGINES:
Engine 1: 6098.6 Hours 3180 Cycles
Engine 2: 6098.6 Hours 3180 Cycles
(Engines on JSSI Program)

AVIONICS

COMM: Triple Collins 422B
LR NAV/FMS: Dual Honeywell NZ-2000/5.2
Software
NAV: Dual Collins 432
GPS: Dual Honeywell
ADF: Dual Collins 462
SAT/AFIS: Allied Signal - Aero C
DME: Dual Collins 442
EGPWS: Allied Signal
XPNDR: Dual Collins TDR-94D Mode S "FLIGHT
ID"

TCAS: Honeywell TCAS II w/Change 7
RAD/ALT: Dual Honeywell RT-300
CVR: Fairchild
HF COMM: Dual Collins w/Selcal
RADAR: Primus 880
INS: Triple Honeywell Laser Nav/Lasertrac
ELT: Artex C406-2 ELT
SATCOM: Honeywell MCS-3000
PHONE: AirCell Access Iridium Sat phone
AP: Honeywell SPZ-8400

(Honeywell HAPP program)

ADDITIONAL FEATURES

RVSM Certified
8.33 Spacing & FM Immunity
Entertainment System with CD/DVD/VHS
Securaplane 500 Security System
PulseLite System
Visionsafe Emergency Vision Assurance System

Tail Logo Lights
8 each 5" Flat Panel Cabin Video Monitors
One 10.4" Flat Panel monitor
Airshow 400 with Genesis System
Multiple Power & Data Ports

INTERIOR

Sixteen-passenger configuration features three distinct seating areas. The forward cabin includes a four-place divan opposite two club chairs. A four-place club group is located at mid-cabin. The aft cabin area includes a four-place divan opposite two club chairs. The interior is furnished in shades of brown, gray and cream with leather chairs, chenille fabric divans and an ultra-suede headliner. The Mahogany woodwork is accented with satin-finish nickel hardware. There is an aft full-service custom galley with a refrigerator, hi-temp oven, microwave, coffee and espresso makers, and generous storage for serviceware and consumables. The lavatory is located aft of the galley.
Original interior completed at Gulfstream in Savannah. Seats, carpet & sidewalls refurbished August 2004

EXTERIOR

Overall white with four accent stripes in green and gold painted at Landmark SPI in August 2004

2 Rue Honoré Labande • 98000 Monaco

Tel: +377 93 25 36 03 Fax: +377 93 50 02 90
www.jetallianceinternational.com

PHOTOGRAPHS



2 Rue Honoré Labande • 98000 Monaco

Tel: +377 93 25 36 03 Fax: +377 93 50 02 90
www.jetallianceinternational.com



2 Rue Honoré Labande • 98000 Monaco

Tel: +377 93 25 36 03 Fax: +377 93 50 02 90
www.jetallianceinternational.com



Specifications/descriptions are provided as introductory information and do not constitute representations or warranties of Jet Alliance International or Jet Alliance International client(s). Accordingly, you should rely on your own inspection of the aircraft. Any proposed transaction is subject to final execution of a contract acceptable in form and substance to Jet Alliance International, its client (s), and their counsel.

2 Rue Honoré Labande • 98000 Monaco

Tel: +377 93 25 36 03 Fax: +377 93 50 02 90
www.jetallianceinternational.com